





Cut dotted lines and round pointed edges in this area.

Do not leave pointy edges, rounded or 45° angled edges will wear better.




Cut dotted lines and round pointed edges in this area.

Do not leave pointy edges, rounded or 45° angled edges will wear better.



Cut dotted lines and round pointed edges in this area.

Do not leave pointy edges, rounded or 45° angled edges will wear better.



Cut dotted lines and round pointed edges in this area.

Do not leave pointy edges, rounded or 45° angled edges will wear better.

